Command Set Specification

| Date | June 24, 2010 |
|------------------|---------------|
| Firmware Version | 1.0.10 |
| Release Date | June 24, 2010 |

This document describes the RS232 command set.



DISCLAIMER:

NOTICE: This document contains proprietary information and may not be reproduced, copied, disclosed or utilized in any way in whole or in part, without the prior written consent of Space Electronics. The information contained herein may also be controlled by the U.S. export control laws. Unauthorized export or re-export is prohibited.

Remote Commands

All commands are in ASCII format and end with a single carriage return <CR>. The meter has four modes of operation; local mode, remote mode, calibration mode, and continuous mode. Specific commands are only available certain meter modes. Below are the list of commands, their functions and the mode they are available in. Following the list of commands each command is documented in detail.

The meter communicates in RS232 using the following specifications.

| Characters | 8 |
|------------|------|
| Parity | N |
| Stop Bits | 1 |
| Baud Rate | 9600 |

The meter can also utilize an optional Ethernet to Meter converter which allows the meter to connect to the computer using a available Ethernet connection on the computer. A driver is then installed on the computer allowing the meter to appear as a virtual serial port on the computer. This allows the same program code written to communicate to the meter to operate with both a serial port or a Ethernet port on the computer.

We do not recommend connecting the meter to the network of your office building. Controlling the IP address of the meter and bandwidth of the network backbone can present challenges to this approach. If you do need to connect the computer communicating with the meter to a office network, we recommend a second dedicated network card be installed in the computer to connect to the meter(s).

| | Standard Command List | | | | | |
|--------------|-----------------------|--|-------|--------|------------|--|
| Command | | | Local | Remote | Continuous | |
| Command | Message | Function | Mode | Mode | Mode | |
| Continuous | COFF | This causes the meter to exit | No | Yes | Yes | |
| Reading Off | GOV | continuous reading mode. This causes the meter to enter No | | *** | | |
| Continuous | CON | This causes the meter to enter | | Yes | No | |
| Reading On | | continuous reading mode. | | | | |
| Flush | FS | Flush Reading FIFO buffer | No | Yes | No | |
| Local | LM | Switches the meter into Local mode. | No | Yes | No | |
| Set Range | SR# | Switches the meter to the range requested. | No | Yes | No | |
| State | ST | Requests the State of the meter. | Yes | Yes | No | |
| Read Battery | RB | Reads the Voltage level of the battery and indicates status. | Yes | Yes | No | |
| Remote | RM | Switches the meter into Remote mode. | Yes | No | No | |
| Reset Meter | RST | Resets the meter to power up state. | Yes | Yes | Yes | |
| Read Value | RV | Reads the present value of the meter. | No | Yes | No | |
| Version | VR | This command reports all version | No | Yes | No | |
| | | information from the meter. | 17 | | | |
| | | | | | | |
| | | ARYIMI | | | | |
| | | ET ARY THE | | | | |
| | | | | | | |
| | a si | | | | | |
| | SPI | | | | | |
| | OPP. | | | | | |
| | OPRI | | | | | |
| | ORRI | | | | | |
| 28 | OPRI | | | | | |
| 2R | ORRI | | | | | |
| 2B | ORRI | | | | | |
| 2B | ORRI | | | | | |
| PR | OPRI | | | | | |
| QR | ORRI | | | | | |
| 2R | ORRI | | | | | |

Detail Documentation Notes:

In the following description any text in bracketed as follows <> is a single ASCII coded character. The value inside the <> symbols is either the direct code value in decimal or the code identifier from the list below.

Example <13> is a Carriage Return

Code List Used

<CR> or <13> is a Carriage Return <LF> or <10> is a Line Feed

All commands are followed by a <CR> character to indicate the completion of the command. All returned responses are followed by a <CR> character as well.

Commands with multiple returning parameters, the parameters are separated by I character.

The following commands are in alphabetical order.

Command Continuous Reading Off

Command Message COFF<CR>

Function This cause the meter to exit continuous reading mode.

Mode Availability Continuous Mode Only

Description

Once in continuous reading mode, this command removes the unit continuous readout.

Example

Send: COFF <CR>

Return: 0<CR>

; Indicates Command Ok

or

1<CR>

; Indicates Unknown Command

or

2<CR>

Command Continuous Reading On

Command Message CON<CR>

Function This cause the meter to enter continuous reading mode.

Mode Availability Remote Mode Only

Description

Once in remote mode, this command sets the unit continuous readout. If this mode every meter reading measured is transmitted to the remote computer. The remote computer must collect the data from the buffered input port or overruns will occur. Once in this command the meter will only accept two commands (COFF or RM) to exit continuous mode. COFF exits the mode and RM exist the mode and resets the meter.

| Range | Format | Over | Wiring | Calib | Hardware | Units |
|----------|---------|----------|----------|-----------|----------|-------------|
| | | Range | Error | Error | Error | 1 |
| | | Format | Format | Format | Format | > |
| No Range | 0.000 | 0.000 | 0.000 | 0.000 | 0.000 |) |
| DIODE | X.XXX | +9.990 | +9.880 | +9.770 | +9.660 | Volts |
| 20 Ohm | XX.XXX | +99.900 | +98.800 | +97.700 | +96.600 | Ohms |
| 200 Ohm | XXX.XX | +999.00 | +988.00 | +977.00 👞 | +966.00 | Ohms |
| 2K Ohm | XXXX.X | +9990.0 | +9880.0 | +9770.0 | +9660.0 | Ohms |
| 20K Ohm | XXXXX | +99900 | +98800 | +97700 | +96600 | Ohms |
| 200K | XXXXXX | +999000 | +988000 | +977000 | +966000 | Ohms |
| Ohm | | | | | | |
| 2M Ohm | XXXXXXX | +9990000 | +9880000 | +9770000 | +9660000 | Ohms |

Example

Send: CON<CR>
Return: 0<CR>

4.600| OVER| ERROR|OK|OK <CR

4.601| OVER| ERROR|OK|OK <CR>4.600| OVER| ERROR|OK|OK <CR>

4.599| OVER| ERRÓR|OK|OK <CR>

; Indicates Command Ok

; Reading 1 |

; Over Range State OVER or OK | ; Wiring Error State ERROR or OK | ; Calibration State OK or BAD |

; Hardware State OK or BAD<CR>

; Reading 3 ; Reading 4

; Reading 2

•••

; Indicates Unknown Command

2<CR>

Command Flush Buffer Command Message FS<CR>

Function This command flushes all data in the reading FIFO buffer.

Mode Availability Remote Mode Only.

Description

This commands flushes all other commands in the input buffer of the meter.

Example

Send: FS<CR> Return: 0<CR>

;Indicates Command Ok

or

1<CR>

; Indicates Unknown Command

or

2<CR>

Command Local Command Message LM<CR>

Function Switches the meter into Local mode

Mode Availability Remote Mode Only

Description

This command switches the system from remote mode into local mode. Local mode activates accepting input from the local buttons on the panel and allows local control of the meter.

Changing to this mode does not change the range of the meter or alter the internal data buffers. It does flush all buffered commands in the incoming communications buffer.

Example

Send: LM<CR>
Return: 0<CR>

or

1<CR>

or

2<CR>

;Indicates Command Q

; Indicates Unknown Command

Command Read Battery
Command Message RB<CR>

Function This command reports the present battery voltage.

Mode Availability Local Mode & Remote Mode.

Description

This commands reads the present battery input voltage in volts. It also returns the battery state (OK or LOW).

Example

Send: RB<CR>

Return: 0|4.600|OK<CR> ; Command OK | Battery Voltage | Battery State OK or LOW

or

1<CR>; Indicates Unknown Command

or

Command Remote
Command Message RM<CR>

Function Switches the meter into Remote mode Mode Availability Local Mode & Calibration Mode Only

Description

This command switches the system from local or calibration mode into remote mode. Remote mode disables the accepting input from the local buttons on the panel and allows remote control of the meter.

Changing to this mode does not change the range of the meter or alter the internal data buffers. It does flush all buffered commands in the incoming communications buffer.

Example

Send: RM<CR> Return: 0<CR>

or

1<CR>

or

2<CR>

; Indicates Command Ok

; Indicates Unknown Command

Command Reset Meter Command Message RST<CR>

Function This command resets the meter returning it to the start up state.

Mode Availability All Modes Only.

Description

This commands resets the meter to its startup state. It return to no range, and zeros all buffers.

Example

Send: RST<CR> Return: 0<CR>

; Indicates Command Ok

or

1<CR>

; Indicates Unknown Commar

or

2<CR>

Command Read Value Command Message RV<CR>

Function This command reads the present measurement value.

Mode Availability Remote Mode Only.

Description

This commands reads the present measurement value. The format of the value can be found in the range chart below.

| Range | Format | Over | Wiring | Calib | Hardware | Units |
|----------|---------|----------|----------|----------|---------------|-------|
| | | Range | Error | Error | Error | 4 |
| | | Format | Format | Format | Format | |
| No Range | 0.000 | 0.000 | 0.000 | 0.000 | 0.000 | 1 |
| DIODE | X.XXX | +9.990 | +9.880 | +9.770 | +9.660 | Volts |
| 20 Ohm | XX.XXX | +99.900 | +98.800 | +97.700 | +96,600 | Ohms |
| 200 Ohm | XXX.XX | +999.00 | +988.00 | +977.00 | +966.00 | Ohms |
| 2K Ohm | XXXX.X | +9990.0 | +9880.0 | +9770.0 | +9660.0 | Ohms |
| 20K Ohm | XXXXX | +99900 | +98800 | +97700 💰 | +96600 | Ohms |
| 200K | XXXXXX | +999000 | +988000 | +977000 | +966000 | Ohms |
| Ohm | | | | | 7 | |
| 2M Ohm | XXXXXXX | +9990000 | +9880000 | +9770000 | +9660000 | Ohms |

Example

Send: RV<CR> Return: 0<CR>

1.2345| OVER| ERROR|OK|OK < CR>

; Indicates Command Ok

Reading |

; Over Range State OVER or OK | ; Wiring Error State ERROR or OK | ; Calibration State OK or BAD | ; Hardware State OK or BAD<CR>

; Indicates Unknown Command

or

<CR>

or

Command Set Range Command Message SR#<CR>

Function Switches the meter to a range condition.

Mode Availability Remote Mode Only

Description

In remote mode, this command sets the range the range index #.

In no range the excitation supply connection is set to ground so that no excitation exists at the squib connections. The meter will display "----" as the readings in this mode, however it will continue to monitor the battery state.

Legal range values are as follows -

| Values of # | | Range |
|-------------|-------------|-------|
| 0 | No Range | |
| 1 | DIODE Range | |
| 2 | 20 Ohm | |
| 3 | 200 Ohm | |
| 4 | 2K Ohm | |
| 5 | 20K Ohm | |
| 6 | 200K Ohm | |
| 7 | 2M Ohm | |

Example

Send: SR0<CR> Return: 0<CR>

or

1<CR>

; Indicates Command Ok

; Indicates Unknown Command

Command State Command Message ST<CR>

Function Requests the state of the meter.

Mode Availability Local Mode, Remote Mode & Calibration Mode Only

Description

This command returns the present mode and range of the meter.

Mode Code Return Values

| Values of # | Range |
|-------------|------------------|
| RM | Remote Mode |
| LM | Local Mode |
| CM | Calibration Mode |

Range Code Return Values

| Values of # | | Range |
|-------------|-------------|----------|
| 0 | No Range | <u> </u> |
| 1 | DIODE Range | |
| 2 | 20 Ohm | |
| 3 | 200 Ohm | |
| 4 | 2K Ohm | |
| 5 | 20K Ohm | |
| 6 | 200K Ohm | |
| 7 | 2M Ohm | |

Example

Send: ST<CR>

Return: 0| RM| SR#<CR>

Indicates Command Okl ; Mode RM, LM, or CMI

; Range #

; Indicates Unknown Command

Command Version
Command Message VR<CR>

Function This command reports all version information from the meter.

Mode Availability Remote Mode Only.

Description

This commands reads the model number, serial number, firmware version number and all the calibration date and values from the meter.

Example

Send: VR<CR>

Return: 0|1234|101-SQB-RAK|1234|1.0.6|2010-12-12<CR>

; Indicates Command Okl

; Cage Codel

; Model Numberl

; Serial Numberl ; Firmware Version

; Calibration Date

or

1<CR>; Indicates Unknown Command

or